Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080171-4

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 12016

RECEIVED FROM: G. V. Control

DATE REC'D: 4-25-57

P.O. NO.: 6521

VENDOR PACKING SLIP NO.: 6221

| CHARGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | OR | ACCT. OR W.O. NO. / S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 321 | 00000 | 3 | 0 | 23 | 1 | | | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 4 | 730125-13 Relay Time Delay 5 Sec. CV # Mf-C4-No. 29 | 4 ✓ | | W Stores |

RECEIVED BY: Barcelos

INSPECTED BY: [illegible]

DATE: 4/25/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC 1089

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 12021

RECEIVED FROM: Plant 19

DATE REC'D: 4-26-57

P.O. NO.:

VENDOR PACKING SLIP NO.:

| CHARGE TO | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | OR | ACCT. OR W.O. NO. / S.O. NO. |
|---|---|---|---|---|---|---|---|---|---|---|
| | 32[illegible] | [illegible]000 | 109 | D | 23 | 2 | 07 | [illegible] | | |

| QUANTITY RECEIVED | DRAWING NO. AND DESCRIPTION | QUANTITY ACCEPTED | QUANTITY REJECTED | REMARKS |
|---|---|---|---|---|
| 6 | 732[illegible]85 Gusset Support<br>IFS #553 | 6 ✓ | | W Stores |

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080171-4

RECEIVED BY: Barcelos

INSPECTED BY: [illegible]

DATE: 4-26-57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC 1089